

The Bendix disc pad DB2088 (Figure 1) was released in 2012 for the Hyundai Sonata rear, and on several Hyundai and Kia vehicles.

It was found some of the new applications used a slightly different pad, that was the same size and shape , which has an extra semi-pierce (lug) on the Inner Backing Plate designed to prevent the caliper piston rotating when the park-brake is applied.




Figure 1 - DB2088

Figure 2 - DB2076

The Bendix part number DB2076 (Figure 2) has been introduced to cater for the applications that require the extra lug.

To help easily distinguish between these two similar pads we have introduced carton labels for both parts with the image of the pad and the list of vehicle applications. With a comment added to show the difference, please see the example labels to the right.

The initial shipment of DB2076 General CT have been branded incorrectly on the pad as DB2088, and they do have the centre semi-pierce (lug). These pads have already been fitted with their wear sensors we have attached a label to the outside of the shrink-wrapped set as shown. They

DB2076

normal General CT cartons with the correct DB2076 label.

will be boxed in the





The Hyundai Sonata changed from using the DB2088 to the DB2076 in June 2010, and the Kia Optima could use either pad depending on what type of park brake system is fitted.

Manufacturer	Model	Year	Variant	Front	Rear	Park
Hyundai	Accent	2010.11	1.6, 1.6td Sedan [RB] (Disc / Disc)	DB2272	DB2076	
Hyundai	Elantra	2011.06	1.8 Sedan [MD]	DB2240	DB2076	
Hyundai	Grandeur	2010.06-2010.11	2.2 CRDi, 3.8 V6 Sedan [TG]	DB1924	DB2076	
Hyundai	i30	2012	1.6td, 1.8 Premium [GD] (280 Disc / 284 Disc with Elec. Park Brake)	DB2240	DB2076	
Hyundai	i30	2012	2.0 SR [GD] (300mm Disc / 284mm Disc with Elec. Park Brake)	DB2348	DB2076	
Hyundai	i40	2011.10	1.7td, 2.0 Sedan [VF]	DB2089	DB2076	
Hyundai	i40	2011.10	1.7td, 2.0 Wagon [VF]	DB2174	DB2076	
Hyundai	Sonata	2007–2010.05	2.0td, 2.4, 3.3 V6 [NF]	DB1924	DB2088	
Hyundai	Sonata	2010.06-2010.11	2.0td, 2.4 V6 [NF]	DB1924	DB2076	
Kia	Optima	2009–2011	2.4 Sedan	DB2089	DB2088	
Kia	Optima	2011	2.4 Sedan (with Mechanical Park Brake)	DB2089	DB2088	
Kia	Optima	2011	2.4 Sedan (with Electric Park Brake)	DB2089	DB2076	
Kia	Rio	2011	1.4, 1.6 MPI [UB]	DB2272	DB2076	
Kia	Soul	2009.04	1.6, 1.6td MPV [AM] (Disc / Disc)	DB1504	DB2088	
Ssangyong	Actyon	2011.09-2012	2.0 TD	DB2034	DB2088	BS3215







FOR MORE INFORMATION

Freecall the Bendix Brake Advice Centre on 1800 819 666 (8am-5pm Monday to Friday EST) or +61 3 5327 0211 from overseas. brakeadvicecentre@bendix.com.au bendix.com.au or bendix.co.nz

